


PHASE 1: PREPARE FOLD



**PHASE 2: FOLD PANEL END
& TUCK EXCESS TO BACK**

ENGLERT
 www.englertinc.com
 800-364-5378

GENERIC BEST PRACTICE ASSEMBLY SHOWN. WATERTIGHTNESS WARRANTY NOT IMPLIED. WHEN SITE CONDITION DIFFERS, SPECIFIC ENGINEERING NECESSARY.

ROOF BREAD PAN FOLD @ RIDGE

SERIES S2000

DETAIL SUBJECT TO CHANGE WITHOUT NOTICE.

Detail #
R06.20