



"OS1" OUTSIDE CORNER TRIM

OUTSIDE CORNER DETAIL



"IS1" INSIDE CORNER TRIM

INSIDE CORNER DETAIL



2.67" x .875 CORRUGATED STANDARD DETAILS

DETAIL SUBJECT TO CHANGE WITHOUT NOTICE.

OUTSIDE & INSIDE CORNER DETAILS

Detail #

W.875.11

GENERIC BEST PRACTICE ASSEMBLY SHOWN. WATERTIGHTNESS WARRANTY NOT IMPLIED. WHEN SITE CONDITION DIFFERS, SPECIFIC ENGINEERING NECESSARY.

Project:
Date:

Scale: NTS

Location:

By: