



"OS2" OUTSIDE CORNER TRIM

OUTSIDE CORNER DETAIL



"IS2" INSIDE CORNER TRIM

INSIDE CORNER DETAIL



www.englertinc.com
800-364-5378

GENERIC BEST PRACTICE ASSEMBLY SHOWN. WATERTIGHTNESS WARRANTY NOT IMPLIED. WHEN SITE CONDITION DIFFERS, SPECIFIC ENGINEERING NECESSARY.

UNIRIB C36 STANDARD DETAILS

OUTSIDE & INSIDE CORNER DETAILS

DETAIL SUBJECT TO CHANGE WITHOUT NOTICE.

Detail #

W.C36.11

Project:

Location:

Date:

Scale: NTS

By: